



POS	ART-NO	DESCRIPTION	TOTAL	POS	ART-NO	DESCRIPTION	TOTAL
1	707-370	Motor housing set SaphirHorse complete	1x	26	707-881	Baseplate charger	1x
3	707-771	Li-Ionic battery Saphir 7.4V/1.6 Ah	1x	27	707-882	Rubber foot	4x
4	707-800-21	Motor complete	1x	28	707-740	Plug EU	1x
5	707-833	PCB clipper	1x	29	707-742	Plug AU	1x
6	707-855	Rubber tap	1x	30	707-743	Plug GB	1x
7	707-847	Turning lever	1x	31	707-744	Plug US-JP	1x
8	707-848	Seal	1x	32	707-822.E	Charger Saphir without power supply unit	1x
9	707-856	Circlip DIN 6799 Ø3,2	1x	32	707-822.A	Charger Saphir incl. power unit and plug EU/GB/US	1x
10	707-886	Washer Ø4x0,5	1x	32	707-822.AU	Charger Saphir incl. power unit and plug AU	1x
11	707-800-20	Excentric cog wheel incl. ball bearing	1x	33	707-295	Plug KR	1x
14	707-557	PT-screw Kombitorx KA30x16	12x	34	707-296	Plug BR	1x
15	707-854-1	Blade support	1x	40	707-668.EU	Power supply unit 110-240V incl. plug EU	1x
16	707-800-25.A	Blade interlock red	1x	40	707-668.AU	Power supply unit 110-240V incl. plug AU	1x
17	707-846	PT-screw Kombitorx KA30x8	1x	40	707-668.GB	Power supply unit 110-240V incl. plug GB	1x
24a	707-875	Upper housing to charger Saphir (Version no longer available)	1x	40	707-668.US	Power supply unit 110-240V incl. plug US-JP	1x
24b	707-875-3	Upper housing to charger Saphir	1x	40	707-668.KR	Power supply unit 110-240V incl. plug KR	1x
25a	707-827	PCB charging station round connector socket inside	1x	40	707-668.BR	Power supply unit 110-240V incl. plug BR	1x
25b	707-827-1	PCB charging station round connector socket outside	1x	40	707-668.ARG	Power supply unit 110-240V incl. plug ARG	1x
				41	707-297	Plug ARG	1x
					722-256	Grease white, tube 70g	
					707-884.A	Set of spare parts Pos. 6 / 7 / 8 / 9 / 10 / 11 / 15 / 16	